



| | | | | |
|---|------------|-----|-----|---|
| D | 09/12/2005 | AGM | AGM | Command barrier changed to MK35-11 Ex0 Li 24VDC |
| C | 23/06/2004 | AGM | AGM | Retransmitted barrier changed to KFD0-CC-Ex1 |
| B | 31/10/2003 | AGM | AGM | Barrier type changed to Turck MK series |
| E | 08/12/2004 | AGM | AGM | 10R resistor added at Terminal 19 |



Lower Farm Road, Moulton Park, Northampton NN3 6XF
Tel +44 (0)1604 790490 Fax +44 (0)1604 790690
www.oranginstruments.com

This drawing remains our property and may NOT be copied or passed onto a Third Party without our written permission.

| Rev | Date | Drawn by | Checked | Description | Title | Project | Job No. | Drawing No. | Rev | | |
|-----|------|----------|---------|-------------|--|------------------------|---------|-------------|-----|-----|------------|
| | | | | | IS200 Actuator Positioner Typical system wiring | IS200 Positioner J1357 | | 1357-005 | E | | |
| | | | | Drawn | | | | | | AGM | 01/10/2003 |
| | | | | Checked | | | | | | AGM | 01/10/2003 |
| | | | | Filename | | | | | | | |